



**UNIVERSAL TURBINE PARTS, INC.**

120 Grouby Airport Road  
 Prattville, AL 36067  
 Phone: 334-361-7853 Fax: 334-361-0290  
 E-mail: sales@UTPparts.com Website: www.UTPparts.com

**ENGINE DISC RECORD SHEET**

<b>ENGINE MODEL:</b>	PT6A-27	<b>TSN:</b>	17046.34	<b>TSO:</b>	4303.7	
<b>ENGINE S/N:</b>	41194	<b>CSN:</b>	28099	<b>CSO:</b>	7549	
				<b>TSHSI:</b>	0	
<b>COMPONENT</b>	<b>P/N</b>	<b>S/N</b>	<b>TSN</b>	<b>CSN</b>	<b>CR</b>	
REAR HUB	3013111	67A618	na	11562	7438	
2ND STAGE	3013712	5M904	na	16169	7831	
3RD STAGE	3011713	8054	na	17497	7503	
IMPELLER	3013176	A7376	na	12140	6860	
CT DISC	3013411	A8999	na	8984	7016	
PT DISC	3022412	72A312	na	7549	12451	
CT Blades	3102401-01	TSO=	497.9			
<b>Mitsubishi (Japan) OH - 1994.</b>						
<b>P&amp;W Repair at TSO 2232 - May 2000.</b>						
<b>Ontario Turbine Repair &amp; Hot Section Inspection - Nov 2007</b>						
<b>Northstar Aerospace Test Cell - Nov 2007</b>						
<b>Accessories</b>	<b>P/N</b>	<b>S/N</b>	<b>TSO</b>			
Prop Governor	8210-004	Not installed				
Fuel Control	2524440-7-6	A7550	724.1			
Fuel Pump	025323-101-03	8950	1138.63			
Start Control	3019109	13133	1138.63			
Bleed Valve	3100829-03	A5020	UNK			
Fuel/Oil Heater	10552E	2817	2046.63			
Ignition Exciter	10-381550-4	98096142C	UNK			